





SLIDING TABLE MODEL G4227 PARTS LIST



COPYRIGHT © 1996 BY GRIZZLY INDUSTRIAL, INC. TX 4-344-567
**Warning: No portion of this manual may be reproduced in any shape
or form without the written approval of Grizzly Industrial, Inc.**
REVISED JULY, 2002. PRINTED IN TAIWAN.

ONLINE PARTS LIST DISCLAIMER

THESE PARTS REPRESENT THE CONFIGURATION OF THE MACHINE AS IT IS CURRENTLY BEING SHIPPED. THE MACHINE CONFIGURATION CAN CHANGE AS PRODUCT IMPROVEMENTS ARE INCORPORATED. IF YOU OWN AN EARLIER VERSION OF THE MACHINE, THIS PARTS LIST MAY NOT EXACTLY DEPICT YOUR MACHINE. CONTACT CUSTOMER SERVICE IF YOU HAVE ANY QUESTIONS ABOUT PART DIFFERENCES. PREVIOUS PARTS LIST VERSIONS ARE NOT AVAILABLE ONLINE.



G4227 Sliding Table

REF	PART #	DESCRIPTION
1	PS13	PHLP HD SCR 10-24 X 1¼"
2	PW03	FLAT WASHER #10
3	P4227003	STOP
4	P4227004	LOCK HANDLE
5	PW16	FLAT WASHER #6
6	P4227006	STOP BRACKET
7	P4227007	POINTER
8	PS16	PHLP HD SCR 6-32 X ¼"
9	P4227009	GIB BOLT
10	P4227010	SCALE
11	P4227011	FENCE
12	PSB11	CAP SCREW 5/16"-18 X 1¼"
13	PN07	HEX NUT 10-24
14	P4227014	TOP RAIL BRACKET
15	PLW04	LOCK WASHER 3/8"
16	P4227016	CAP SCREW 3/8"- 16 X 23/8"
17	P4227017	END CAP
18	P4227018	TOP RAIL
19	P4227019	SPACER
20	PS22	PHLP HD SCREW 10-24 X 5/8"
21	P4227021	IDLER WHEEL W/BUSHING
22	P4227022	RUBBER RING
23	P4227023	FRONT STOP
26	PR01M	SNAP RING 10MM
27	P6200	BEARING 6200-2RS
28	P4227028	BEARING SHAFT
29	P4227029	T-BOLT, SHORT
30	PW02	FLAT WASHER 3/8"
32	P4227032	LOCK HANDLE
33	PLW03	LOCK NUT 5/16" - 18
34	P609	BEARING 609-2RS
35	P4227035	V-ROLLER
36	PSS03	SETSCREW ¼"-20 x 3/8"
37	P4227037	ECCENTRIC SHAFT
38	P4227038	TABLE FRAME
39	P4227039	CAP SCREW M10-1.5 x 55
40	PN08	HEX NUT 3/8" - 16
41	PSB04	CAP SCREW ¼" - 20 x ½"

REF	PART #	DESCRIPTION
42	PLW02	LOCK WASHER ¼"
43	P4227043	WORK TABLE
44	P4227044	SCREW 3/8"
45	P4227045	DEGREE SCALE
46	P4227045	BUSHING
47	P4227047	SPACER
48	P4227048	ECCENTRIC BUSHING
49	P4227048	BUSHING MOUNT BRACKET
50	P4227050	SCREW ½"
51	PW06	FLAT WASHER ¼"
52	PSB05	CAP SCREW ¼"-20 X ¾"
53	PSS03	SETSCREW ¼"-20 X 3/8"
54	P4227054	T-BOLT, LONG
55	P4227055	BRACKET
56	PN05	HEX NUT ¼"-20
57	PB31	HEX BOLT ¼"-20 X 1"
59	P4227059	SHAFT
60	P4227060	SLIDING BRACKET
61	P4227061	LOCKING BRACKET
63	P4227063	LOCK HANDLE
64	PB51	HEX BOLT ¼"-20 X 3/8"
65	PW02	FLAT WASHER 3/8"
66	P4227066	STUD
67	P4227067	BOTTOM BRACKET
68	P4227068	BOTTOM RAIL
69	P4227069	PLUG
70	PN02	HEX NUT 5/16"-18
71	P4227071	HANDLE
72	P4227072	SUPPORT BRACKET
73	PN13	HEX NUT ½"-13
74	PLW07	LOCK WASHER ½"
75	P4227075	BEARING BRACKET
76	P4227076	SPACER
77	P6304	BEARING 6304-2RS
78	P4227078	AXLE
79	PB05	HEX BOLT ¼"-20 X ¾"
80	PW07	FLAT WASHER 5/16"
81	PB03	HEX BOLT ¾"-18 X 1"