


# H0775 Parts Breakdown and List



# H0775 Parts List

REF	PART #	DESCRIPTION
A	P51101	THRUST BEARING 51101
B	PH4016447	SPACER M12 X 8
C	PH4016448	STAR WASHER M12
D	PLN09	LOCKING NUT M12-1.25
1	PH0775001	END BLOCK
2	PH0775002	SLIDE BLOCK
3	PH0775003	PIN 12 X 50
4	PSS16M	SET SCREW M8-1.25 X 10
5	PH0775005	CAP SCREW M5-.8 X 45
6	PH0775006	MAIN BRACKET
7	PW01M	FLAT WASHER, 8MM
8	PH0775008	PIN 5 X 25
9	PSB13M	CAP SCREW M8-1.25 X 30
10	PS07M	PHLP HD SCR M4-.7 X 8
11	PH0775011	COVER
12	PSS25M	SET SCREW M6-1 X 20
13	PN01M	HEX NUT M6-1
14	PH0775014	SLANT IRON
15	PSB06M	CAP SCREW M6-1 X 25
16	PH0775016	ADJUSTING BLOCK
17	PH0775017	SLIDE
18	PH0775018	GIB
19	PH0775019	ROUND NUT

REF	PART #	DESCRIPTION
20	PH0775020	THREADED ROD
21	PH0775021	SUPPORTING BLOCK
22	PH0775022	HANDLE
23	PH0775023	PIN 3 X 18
24	PH0775024	SIGN PLATE
25	PH0775025	COPYING MODE
26	PH0775026	MOVING BLOCK
27	PSB13M	CAP SCREW M8-1.25 X 30
28	PH0775028	POSITIONING SCREW
29	PH0775029	COPYING PLATE
30	PSB13M	CAP SCREW M8-1.25 X 30
31	PH0775031	PHLP HD SCR M3-.5 X 8
32	PH0775032	SIGN PLATE
33	PH0775033	SUPPORTING ROD
34	PH0775034	VERTICAL ROD
35	PSB01M	CAP SCREW M6-1 X 16
36	PH0775036	BRACKET
37	PSB01M	CAP SCREW M6-1 X 16
38	PSS11M	SET SCREW M6-1 X 16
39	PH0775039	CLAMPING PLATE
40	PSB45M	CAP SCREW M8-1.25 X 45
41	PSB02M	CAP SCREW M6-1 X 20